

#### Pipeline Integrity Program – Brief History

- PIP has focused primarily on AC pipe
- PIP identified cohort CM-450-D-Metallic or "1951 Cohort" (Cohort) in the "high breaks" category
- PICA HydraSnake recommended by PIP consultant
- Board awarded contract March 2025





Table 1. Cohort performance over last 13 years

| Cohort Group      | Location   | Length (Miles) | Number of Breaks | Break Rate (Breaks/Mile/Year) |
|-------------------|--|----------------|------------------|-------------------------------|
| CM-450-D-Metallic | Between Placentia and Newport and Wilson and 19 <sup>th</sup> Street | 5.6            | 33               | 0.45                          |




#### HydraSnake Inspection Work Area



3 | June 11, 2025



## Hydrasnake – How Does It Work?







## **Avocado Street Inspection Route**

- Fairview to College
- 123 meters
- 11 hydrants
- 1,700 ft



5 | June 11, 2025

# Maple Ave Inspection Route

- Yorkshire St to 19th St
- 91 meters
- 6 hydrants
- 1,300 ft



#### Sample from Avocado Street Pipeline



Sample taken from recent repair of cement mortar lined/coated (CMLC) steel pipe in Avocado Street.



#### **Public Outreach**

- Bilingual canvassing was completed by Murakawa Communications on Thursday, June 5.
- Mesa Water staff will do a second notification via doorhanger on Thursday, June 12 and Friday, June 13.
- Mesa Water Notify alert to go out on Thursday, June 12 and Friday, June 13.
- Construction hotline will be listed on all notices.



# **Next Steps**

- 1. Canvass (complete)
- 2. Inspection
- 3. Results



MesaWater DISTRICT:

QUESTIONS?

